

FIG. 1.




FIG. 2




FIG. 3




FIG. 4




FIG. 5




FIG. 6




FIG. 7




FIG. 8




FIG. 9




FIG. 10





FIG. 11


ST 01

Fit spacers on catalyst



ST 02

Fit the resulting catalyst assembly into a pipe portion



ST 03

Throttle the pipe portion




FIG. 12




FIG. 13




FIG. 14(a)




FIG. 14(b)




FIG. 15




FIG. 16




FIG. 17




FIG. 18(a)




FIG. 18(b)




FIG. 19(a)




FIG. 19(b)




FIG. 20




FIG. 21




FIG. 22




FIG. 23




FIG. 24




FIG. 25




FIG. 26
BACKGROUND ART




FIG. 27

BACKGROUND ART